

BUILDING SAFETY CERTIFICATENo. 1824 / AE IIIDated: 24-03-2025

Certified that the existing building Sunbeam School Varuna (name of the building or premises) at the Sunbeam School Varuna, 858, Central Jail Road, Sikraul, Varanasi, Uttar Pradesh - 221002 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)
No. of Floor(s) in the Block	4	5	4	-

The building is owned/occupied by Sunbeam School Varuna (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Nirman Khand (Bhawan) PWD, Varanasi, Uttar Pradesh (Name of Department/ Govt.) on 26-03-2025 (date of inspection) in the presence of Mr. Manoj Kumar Srivastava, Manager, Sunbeam School Varuna, 858, Central Jail Road, Sikraul, Varanasi (UP)-221002 (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 24-03-2025 for a period of Five years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The school building must undergo regular inspections to ensure its upkeep.
2. Regular maintenance of the school building must be ensured.
3. ---
4. ---

Issued on _____ at Varanasi by.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Shri Dhananjay Yadav
सहायक अभियन्ता

Name Shri Dhananjay Yadav

Designation : Junior Engineer

Name & Address of Department/Office:

Nirman Khand (Bhawan) PWD, Varanasi, UP

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only.



Dr. Anupama Mishra
Principal
Sunbeam School Varuna
Varanasi-221002